



STEP 1

- 1. CUT CABLE LENGTH.
- 2. CLEAN AND SOLDER COAT CABLE END TO DIMENSION SHOWN.



STEP 2

1. TRIM CABLE END TO DIMENSION SHOWN.



STEP 3

- 1. VERIFY THAT THE CONTACT HOLE IN THE CONNECTOR IS ALIGNED WITH THE CABLE ENTRY.
- 2. INSERT CABLE INTO BODY ASSEMBLY AS SHOWN AND VERIFY THAT THE CENTER CONDUCTOR ENTERS CONTACT.
- 3. PUSH CABLE UNTIL CABLE OUTER CONDUCTOR BOTTOMS OUT.
- 4, SOLDER CABLE TO BODY WHERE SHOWN.
- 5. FOR REGION SHOWN NO SOLDER ALLOWED ON CENTER CONDUCTOR OR BODY
- 6. SOLDER CABLE CENTER CONDUCTOR TO CONTACT WHERE SHOWN.
- 7. ELECTRICAL TEST.
- 8. USE A FLAT PUSHER TOOL AND ARBOR PRESS AND INSTALL ACCESS CAP FLUSH WITH BODY.

	USED ON				DATE			<u> </u>				
				PREP.	S0		08/07/15	KH	7 H	UBER	R+SUHN	IER
	UNLESS OTHERWISE SPECIFIED			ELEC.							A stro	ا به ا
	MAX. RADIUS OR CHAMFER. SURFACE FINISH 63 RMS		MECH. GSG			08/12/15 TH		THIS DRAWING CONTAINS PATENTABLE AND PROPRIETARY INFORMATION. THE DESIGN CANNOT BE USED WITHOUT WRITTEN PERMISSION OF HUBER + SUHNER ASTROLAB.				
			Q.C.		IN							
	FRACTIONS ± 1/32			TITLE								
	×	±	.015	CONNECTOR, SMP FEMALE, 90° TO .086 [2.18] DIA. S/R								
	xx	±	.010	1	COMMECTO	۱, ۱۱۱۱	I LI IALL,	, 70	0 .00	J [2.10] D	IA. 37 K	
•	xxx	±	.005		ACCORD WITH U.S.	SCALE	CODE IDENT.		DWG NO.			REV
	ANGLES	±	1-		DEPT. OF COMM. SCREW THD. STDS. FOR FEDERAL SERVICES 1950 SUPL.		1630	. 1	26	CMD	E 0 2 2	_
)	DO NOT SCALE DRAWING			TO HANDBOOK H 28.		5:1	16301		26_SMP-50-2-		-50-2-2	_