



12-August-2014

Si5347/46, Si5345/44/42, Si5341/40 Silicon Revision A1 Errata

Errata Status Summary

Errata #	Title	Impact	Status
1	Output frequency limited to 710 MHz.	Major	May be fixed in a future revision.
2	OSC startup issue w/ XTALs if Tj > 110 °C.	Major	Fixed in silicon revision B.
3	Input-to-Output delay is not consistent.	Major	No workaround. Will be fixed in a future revision.
4	Output-to-Output skew is not consistent.	Major	No workaround. Will be fixed in a future revision.
5	LVC MOS Hi-Z mode impedance too low.	Major	No workaround. Will be fixed in a future revision.
6	LOS and OOF sticky status bits cannot be cleared.	Minor	No workaround. Will be fixed in a future revision.

Impact definition: Each erratum is marked with an impact, as defined below:

- Minor – Workaround exists.
- Major – Errata that do not conform to the data sheet or standard.
- Information – The device behavior is not ideal but acceptable. Typically, the data sheet will be changed to match the device behavior.
- This document applies to Ordering Part Numbers (OPNs) which refer to product Revision A (silicon revision A1). For example: Si5345A-**A**-GM or Si5341A-**A**xxxxx-GM, where xxxxx is the custom OPN ID.
- Silicon revision B will have OPNs with B in the product revision. For example: Si5345A-**B**-GM or Si5341A-**B**xxxxx-GM, where xxxxx is the custom OPN ID.

Errata Details

1. **Description:**

The VCO operating frequency range limits the maximum generated clock output frequency.

Impact:

Frequencies can be generated up to 710 MHz and not 800 MHz as stated in the data sheet. ClockBuilder Pro currently limits output frequencies to 710 MHz.

Workaround:

There is no workaround for this issue at this time.

Resolution:

This limitation may be fixed in a future revision.

Description:

The oscillator circuit (OSC) may not start up when running the chip at high temperatures. The ESD protection circuit on XA/XB interacts with an internal regulator for the OSC circuit at start up. The problem occurs when the junction temperature is above 110 °C.

Impact:

If the chip is powered-up, or a hard or soft reset is performed at high temperatures, the DSPLL will not be able to achieve lock and output clocks will not be generated.

Workaround:

There is no workaround for this issue. Refer to ClockBuilder Pro's power dissipation report to help determine your design's effective junction temperature.

Resolution:

This issue is fixed in silicon revision B.

2. **Description:**

The input-to-output delay is not consistent when running the chip at high temperatures. The problem occurs when the junction temperature is above 110 °C.

Impact:

If the chip is powered-up, or a hard or soft reset is performed at high temperatures, the input-to-output delay may exceed the data sheet specification.

Workaround:

There is no workaround for this issue.

Resolution:

This erratum will be fixed in a future revision.

3. **Description:**

The output-to-output delay is not consistent when running the chip at high temperatures. The problem occurs when the junction temperature is above 110 °C.

Impact:

If the chip is powered-up, or a hard or soft reset is performed at high temperatures, the output-to-output delay may exceed the data sheet specification of 100 ps.

Workaround:

There is no workaround for this issue.

Resolution:

This erratum will be fixed in a future revision.

4. **Description:**

An LVCMOS output can be configured to disable in a low logic state, a high logic state, or in high-impedance mode. The disable in high-impedance state does not meet the data sheet specification.

Impact:

The LVCMOS high-impedance mode should not be used.

Workaround:

Select the disable state as stop-high or stop-low.

Resolution:

This erratum will be fixed in a future revision.

5. **Description:**

LOS and OOF sticky status bits cannot be cleared unless its fault monitor is disabled.

Impact:

LOS and OOF sticky (flag) bits will always remain set whenever asserted. Clearing the sticky bit(s) will have no effect.

Workaround:

It is possible to clear a sticky bit by temporarily disabling its fault monitor. Once disabled, the bit can be cleared and the fault monitor re-enabled.

Resolution:

This erratum will be fixed in a future revision.