

PRODUCT CHANGE NOTIFICATION

Product Category LABELING SYSTEMS 20220615-1

Product Group ID AND SAFETY

ISSUE DATE: 15-Jun-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Part numbers LS8E, LS8EQ, LS8E-KIT, LS8EQ-KIT, LS8E-KIT-ACS, LS8EQ-KIT-ACS, LS8E-KIT-ACE, and LS8EQ-KIT-ACE will be discontinued. The replacement for the LS8E and LS8EQ printers is part number MP300 for North America, and part number MP300/E for international use. The label cassettes and accessories for the LS8E and LS8EQ will not be discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	6	15
Old product discontinuation date*	2022	12	31

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
LS8E	Complex	MP300
LS8EQ	Complex	MP300
LS8E-KIT	Complex	MP300
LS8EQ-KIT	Complex	MP300
LS8E-KIT-ACS	Complex	MP300
LS8EQ-KIT-ACS	Complex	MP300
LS8E-KIT-ACE	Complex	MP300/E
LS8EQ-KIT-ACE	Complex	MP300/E