

## Information note

**Topic** NEO-M8L, NEO-M8U: New firmware available

UBX-20014803

**Author** Martin Wallebohr, Mathias Vetter

**Date** 30 April 2020

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit [www.u-blox.com](http://www.u-blox.com).  
Copyright© u-blox AG.

## 1 Affected Products

Product name	Previous order codes	New order code	New firmware
NEO-M8L	NEO-M8L-0, NEO-M8L-04B	NEO-M8L-05B	ADR 4.31
NEO-M8U	NEO-M8U-0, NEO-M8U-04B	NEO-M8U-05B	UDR 1.31

## 2 Type of change

- Hardware modification
- Firmware update
- Documentation update
- Others: New module versions recommended for new designs

## 3 Description

Due to new firmware release of ADR 4.31 and UDR 1.31 new order codes are available now.

New features and enhancements are now available with firmware versions ADR 4.31 and UDR 1.31. See referenced documents [1] and [2] for more details.

## 4 Schedule

Product name	Order code	Firmware	Availability
NEO-M8L	NEO-M8L-05B	ADR 4.31	May 2020 (ES), July 2020 (IP)
NEO-M8U	NEO-M8U-05B	UDR 1.31	May 2020 (ES), July 2020 (IP)

## 5 Customer impact and recommended action

- For new designs and projects it is highly recommended to use new module versions.
- Former product versions might be discontinued at later stage.

## 6 Reference documents

[1] Release Notes ADR 4.31– NDA required, UBX-20009341

[2] Release Notes UDR 1.31– public, [UBX-20013174](#)

[3] NEO-M8U SPG 3.01 UDR 1.31, [firmware](#)

Reference documents are available via local sales offices: [sales-network-offices](#)