

Product Category		STRONGHOLD			20201006-1
Product Group		STRONGHOLD			
ISSUE DATE:					_
IMPACTED REGIONS:	✓ NA	✓ EMEA	LATAM	AP	_
REASON FOR CHANGE:	✓ DISCONTINUATION				
	OTHER				
DESCRIPTION OF CHANGE: (Required)				
Photos/Drawing (where app	licable)				
IMPACTED PART NUMBER	S AND REPLACEMEN	IT PART NUMB	ERS: (where appl	icable)	
IMPACTED PART NUMBER Reference Page 2 / Linked		IT PART NUMB	ERS: (where appl	<u>icable)</u>	

	Year	Month	Day
SCHEDULE FOR CHANGE	(YYYY)	(MM)	(DD)
New product sample availability date	2020	10	6
Old product discontinuation date*	2021	1	6

^{*}Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Impacted Part NumbersCompatibility TypeReplacement PartPAM075NY-A-CDirectSMP16A-CPAM100NY-A-CDirectSMP12A-C