



# PRODUCT UPDATE MEMO

## SURGE PROTECTIVE DEVICES

REVISED JUNE 24, 2022 -  
Part Numbers Added on Page 2



### Bourns Adjusts Minimum Order Quantity (MOQ) and Multiple Order Quantity (Mult) for Select Surge Protective Devices

Riverside, California – May 20, 2022 – Effective immediately for new orders, the Minimum Order Quantity (MOQ) has changed for select Bourns® Surge Protective Devices. The Multiple Order Quantity (Mult) has also changed for select Bourns® Surge Protective products. A full list of the new changes in the MOQ and Mult for the affected Bourns® Surge Protective Devices is included in the table below.

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Affected Part Number	Old MOQ	New MOQ	Old Mult.	New Mult.
1210-3S-120	3	24	3	24
1210-1S-230	8	96	8	96
1210-1S-400	8	96	8	96
1210-2S-400	4	48	4	48
1210-3S-400	3	24	3	24
1210-1S-600	4	96	4	96
1250-4S-120	2	24	2	24
1250-4S-230	2	24	2	24
1250-1S-400	8	96	8	96
1250-2S-400	4	48	4	48
1214-240S	1	4	1	4
1214-208Y	1	4	1	4
1214-277Y	1	4	1	4
1214-480D	1	4	1	4
1224-240S	1	4	1	4
1224-208Y	1	4	1	4

SPD2202 REV

**(PART NUMBERS ADDED)**

Affected Part Number	Old MOQ	New MOQ	Old Mult.	New Mult.
1224-277Y	1	4	1	4
1224-480D	1	4	1	4
1251-120S-N1	1	12	1	12
1251-120S-N2	1	12	1	12
1251-208Y-N1	1	12	1	12
1251-208Y-N2	1	12	1	12
1251-240S-N1	1	12	1	12
1251-240S-N2	1	12	1	12
1252-120S-N1	1	12	1	12
1252-120S-N2	1	12	1	12
1252-208Y-N1	1	12	1	12
1252-208Y-N2	1	12	1	12
1252-240S-N1	1	12	1	12
1252-240S-N2	1	12	1	12
1210-1S-120	8	96	8	96
1210-2S-120	4	48	4	48
1210-4S-120	2	24	2	24
1210-2S-230	4	48	4	48
1210-3S-230	3	24	3	24
1210-4S-230	2	24	2	24
1210-4S-400	2	24	2	24
1210-3S-600	2	24	2	24
1250-1S-120	8	96	8	96
1250-2S-120	4	48	4	48
1250-3S-120	3	24	3	24
1250-1S-230	8	96	8	96
1250-2S-230	4	48	4	48
1250-3S-230	3	24	3	24
1250-3S-400	3	24	3	24
1250-4S-400	2	24	2	24
1250-1S-480	8	96	8	96
1250-3S-480	3	24	3	24
1320-S-12	8	96	8	96
1320-S-24	8	96	8	96
1320-S-48	8	96	8	96
1320-S-75	8	96	8	96
1320-S-110	8	96	8	96



Affected Part Number	Old MOQ	New MOQ	Old Mult.	New Mult.
1420-PV-1000	3	24	3	24
1977-09-A00	10	100	10	100
1977-09-A01	10	100	10	100
1977-09-A02	10	100	10	100
1977-50-A01	10	100	10	100
1977-09-A03	10	100	10	100
1977-25-A00	10	100	10	100
1977-25-A01	10	100	10	100
1977-25-A02	10	100	10	100
1977-25-A03	10	100	10	100
1977-50-A00	10	100	10	100
1977-50-A02	10	100	10	100
1977-50-A03	10	100	10	100