




Subject: PCN 115 b - Change to the flange of IP-2X6 modules

Description: As part of our continuous improvement process regarding the quality of our products LEDiL has changed the mechanical design of the flange on some of our STRADA-IP-2X6 and HB-IP-2X6 lenses. Changes improve durability of modules around screw towers and don't have other mechanical or any optical influences on the performance or use of the products.

Affected products:
C14229_HB-IP-2X6-WWW
CS14263_HB-IP-2X6-WWW
C14017_STRADA-IP-2X6-DWC-90
CS14145_STRADA-IP-2X6-DWC-90
C12861_STRADA-IP-2X6-DWC
CS12862_STRADA-IP-2X6-DWC

Time line: We will deplete existing stock before shipping new parts.

Changes:



Contact information: Tero Mäkinen
LEDIL Oy
Salorankatu 10
24240 SALO, FINLAND
tero.makinen@ledil.com