



Not Recommended for New Design: EEC-HZ, HW, HL Series Electric Double Layer Capacitors (Gold Capacitors)

NRFND.PG19.06.25.2019

06.25.2019

About This Notice:	The EEC-HZ, HW and HL Series of Electric Double Layer Capacitors (Wound Type) have been designated Not Recommended For New Design by Panasonic.
Features:	
Effective Date:	July 1, 2019
Affected Parts and/or Replacements:	See Attached.
Datasheet(s):	See Attached.
Notes:	

Series	Affected Parts
HZ	EEC-HZ0E335
HZ	EEC-HZ0E475
HZ	EEC-HZ0E106
HW	EEC-HW0D226
HW	EEC-HW0D306
HW	EEC-HW0D506
HW	EEC-HW0D706
HL	EEC-HL0E506
HL	EEC-HL0E107
HL (85°C)	EEC-HL0E255
HL (85°C)	EEC-HL0E405
HL (85°C)	EEC-HL0E755
HZ	EEC-HZ0E106B
HZ	EEC-HZ0E106D
HW	EEC-HW0D406D
HW	EEC-HW0D506K
HW	EEC-HW0D726H
HW	EEC-HW0D726H2
HW	EEC-HW0D726H3
HL	EEC-HL0E476E
HL	EEC-HL0E476H3