

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
90	012	003	0000004533	4833.2200	Audio Socket 6.3MM 2P		
90	012	003	0000004533	4833.2220	Audio Socket 6.3MM 2P		
90	012	003	0000004533	4833.2230	Audio Socket 6.3MM 2P		
90	012	003	0000004533	4833.2300	Audio Socket 6.3MM 3P		
90	012	003	0000004533	4833.2320	Audio Socket 6.3MM 3P		
90	012	003	0000004533	4833.2330	Audio Socket 6.3MM 3P		

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

## 2 Type of change

The metal finishing will be changed to tin plating.

## 3 Detailed description of change

The surface finishing of the metal parts will be changed from silver plating to tin plating. Quality and characteristics of the audio sockets are not affected by this change.

## 4 Reason of change

Due to production process and product costs the metals parts cannot be offered with silver plating anymore. Tin plating guarantees more stable quality and is most widely used on other audio connectors and audio jacks.

## 5 Release date

The change will be rolled-out starting ww 01/2016 (date code 1601 or higher on the label).

## 6 Impact of change and recommended action

Form: No No change of the form but the metal parts are slightly less shiny  
 Fit: No There are no dimensional changes  
 Function: No This is a non-functional change  
 Production Site: No There is no change of the production site  
 Product Label: No There is no change on the label

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Data Sheet 4833.2200</a>	
<a href="#">Data Sheet 4833.2220</a>	
<a href="#">Data Sheet 4833.2230</a>	
<a href="#">Data Sheet 4833.2300</a>	
<a href="#">Data Sheet 4833.2320</a>	
<a href="#">Data Sheet 4833.2330</a>	

Product Change Notification					PCN 4833.22XX, 4833.23XX		
owner	creation date	release date	released by	change order no	rev	page	D10-001-298
hotzar	2016-02-01	2016-02-01	hotzar	2009044	A	1 of 1	