



---

# ESSENTRA

## COMPONENTS

27 July 2018

To whom it may concern:

This letter is to notify you of a part number changes that Essentra Components has made. This is only a part number change; there has been absolutely no change to the product itself. You are being notified because you have purchased one or more of these parts in the past 2 years. The following are a list of the part numbers that may affect your company.

<u>Old Part #</u>	<u>New Part #</u>
FR001A	27RT187500
FR002A	27RT187550
FR003A	27RT187700PPB
FR004A	27RT250440
FR005A	27RT250800
FR006A	27RT2811000
FW0010A	16FW002032
FW0030B	16FW002093B
FW0040A	16FW002125
FW0042A	17W01815
FW0045A	17W02190
FW0050A	16FW004032
FW0060B	16FW004062B
FW0080A	16FW004125
FW0082B	17W02181B
FW0090A	16FW006032
FW0110A	16FW006093
FW0110B	16FW006093B
FW0190A	16FW010093
FW0202A	17W04376
FW0203A	17W04373
FW0206B	17W03768B
FW0210A	16FW250032

---

**ESSENTRA COMPONENTS**

3123 Station Road  
Erie, PA 16510  
United States of America

T (800) 899-9440  
F (814) 899-2586  
E [saleserie@essentracomponents.com](mailto:saleserie@essentracomponents.com)  
[www.essentracomponents.com](http://www.essentracomponents.com)



---

# ESSENTRA

## COMPONENTS

FW0250A	16FW312032
FW0260A	16FW312062
FW0292A	17W07402
FW0450A	17W12503
HN-M4-01	04M040070HN
PPR-T1	61PRT0125
RW375032A	16FWRT375032
RW4032A	16FWRT004032
RW4050A	16FWRT004050
RW4125A	16FWRT004125
RW6032A	16FWRT006032
SWS0330A	13SP052
SWS1550A	13SP114
SWS2270A	13SP212
WS0330A	12SWS0439
WS0670A	12SWS0802
WS0890A	12SWS0811
WS0910A	12SWS0832
WS1780A	12SWS2587
WS1790A	12SWS3025
WS1820A	12SWS3690
WS1830A	12SWS3016
XT3120250A	27XT3120250
XT3120375A	27XT3120375
XT3120625A	27XT3120625
XT3120750A	27XT3120750
XT3120875A	27XT3120875
XT3121000A	27XT3121000
XT3121250A	27XT3121250
XT3121500A	27XT3121500



---

**ESSENTRA**

COMPONENTS

Please let me know if you have any questions.

Best Regards,

Greg P. Mifsud  
Director of Product Management