



Product Change Notification

PCN#: TIES AND TERMINALS-

Issue Date: 22Jul2019

Impacted Regions: NA EMEA LATAM AP

Reason for Change: Discontinuation Other Part # Change

DESCRIPTION OF CHANGE:

Due to the latest RoHS standard update, there has been a material change to select Panduit terminal insulation. The specific part numbers can be found in the "Impacted Part Number(s)" chart below and span a family of pin terminals, piggy-back disconnects, fork terminals, and ring terminals. This material change is minor and does not affect performance in any way. The part numbers will be changed for SKU management convenience to distinguish previous iterations from the current compliant products.

PHOTOS/DRAWING *(where applicable)*



**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

Schedule for Change	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2019	07	22
Old product discontinuation date*	2019	07	22

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.



IMPACTED PART NUMBER(s)	*REPLACEMENT PART NUMBER(s)
DV14-250P-E	DV14-250P-EYY
DV14-250P-L	DV14-250P-LYY
DV14-250P-M	DV14-250P-MYY
DV18-250P-LY	DV18-250P-LYY
DV18-250P-MY	DV18-250P-MYY
EDV14-250P-L	EDV14-250P-LYY
EDV18-250P-L	EDV18-250P-LYY
EV10-P55-Q	EV10-P55-QYY
PV10-P55-DY	PV10-P55-DYY
PV10-P55-E	PV10-P55-EYY
PV10-P55-LY	PV10-P55-LYY
PV22-10R-CY	PV22-10R-CYY
PV22-10R-MY	PV22-10R-MYY
PV22-2R-CY	PV22-2R-CYY
PV22-2R-MY	PV22-2R-MYY
PV22-4F-CY	PV22-4F-CYY
PV22-4F-MY	PV22-4F-MYY
PV22-4R-CY	PV22-4R-CYY
PV22-4R-MY	PV22-4R-MYY
PV22-6F-CY	PV22-6F-CYY
PV22-6F-MY	PV22-6F-MYY
PV22-6R-CY	PV22-6R-CYY
PV22-6R-MY	PV22-6R-MYY
PV22-8R-CY	PV22-8R-CYY
PV22-8R-MY	PV22-8R-MYY
DMV1-63P-LY	DV18-250P-LYY
DMV1-63P-XY	DV18-250P-EYY
DMV2-63P-L	DV14-250P-LYY
EDV14-250P-E	EDV14-250P-LYY
EDV18-250P-EY	EDV18-250P-LYY