



Product Change Notification		Date Sept 10, 2020
Product	Connect IT 4/16/48/Mini	

Description of change	New firmware version 20.8.22.32 available for all Connect IT products. This is a major production release. Digi recommends all customers upgrade their Connect IT products to firmware v20.8.22.32
------------------------------	--

Reason for Change	New Firmware Version 20.8.22.32 provides: <ul style="list-style-type: none">• New Features• Enhancements• Bug Fixes• Security Fixes See Release Notes for more details.
--------------------------	--

Product Notice	<p>A new stable firmware version has been released for the Connect IT products, version 20.8.22.32. Use the link below to view the full list of changes, features, and fixes included in the new firmware.</p> <p>Connect IT Release Notes</p> <p><u>To take advantage of the new features, you must take action to upgrade your device.</u> Refer to the instructions to upgrade your firmware in the release notes above for more information.</p> <p>Any questions or concerns about the new firmware, or for assistance upgrading your device(s), please contact the Digi Support team at tech.support@digi.com.</p>
-----------------------	--

Affected Part Numbers	IT16-1002, IT48-1002, IT01-M100, ASB-5402-RM
------------------------------	--

Timing of Change	Effective Immediately
-------------------------	-----------------------