



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 265742

2. Date of Announcement: January 20, 2016

3. Series:

- TFC - .050 X .050 TERMINAL STRIP

4. Part #'s Affected


- TFC-1XX-XX-XX-D-XX

5. Description of Change:

The voids in the keying notch location are being changed from visible/through to blind/filled.

6. Method of Identifying Change

The change to the void can be seen when viewing the connector body with no magnification needed.



7. Reason for Change:

The existing mold has a shut off condition that yields flash in the void during the molding cycle. By removing the voids, this condition is eliminated.

8. Impact of Change on Form, Fit, or Function:

- Form - The voids at the keying notch location are being removed.

9. Projected Implementation Date: February 20, 2016