

PRODUCT CHANGE NOTIFICATION

PCN#: COPPER, OUTLETS, SURFACE RACEWAY 20180821-1

ISSUE DATE: 8/21/2018



IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

Discontinuation of Pan-Net **CJA*88*** style jack modules, also known as "Avaya Style Jack Modules" or "Module for Avaya Faceplates".

Photos of Avaya Style Jack Modules (Note square face outline and clips on side to snap into faceplate)



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

| SCHEDULE FOR CHANGE | Year (YYYY) | Month (MM) | Day (DD) |
|--------------------------------------|-------------|------------|----------|
| New product sample availability date | | | |
| Old product discontinuation date* | 2018 | 12 | 21 |

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

| IMPACTED PART NUMBER(s) | REPLACEMENT PART NUMBER(s) |
|-------------------------|----------------------------|
| CJA5E88TBL | CJ5E88TGBL |
| CJA5E88TBU | CJ5E88TGBU |
| CJA5E88TEI | CJ5E88TGEI |
| CJA5E88TGBL | CJ5E88TGBL |
| CJA5E88TGBU | CJ5E88TGBU |
| CJA5E88TGEI | CJ5E88TGEI |
| CJA5E88TGGR | CJ5E88TGGR |
| CJA5E88TGIG | CJ5E88TGIG |
| CJA5E88TGIW | CJ5E88TGIW |
| CJA5E88TGOR | CJ5E88TGOR |
| CJA5E88TGR | CJ5E88TGGR |
| CJA5E88TGRD | CJ5E88TGRD |
| CJA5E88TGVL | CJ5E88TGVL |
| CJA5E88TGWH | CJ5E88TGWH |
| CJA5E88TGYL | CJ5E88TGYL |
| CJA5E88TIG | CJ5E88TGIG |
| CJA5E88TOR | CJ5E88TGOR |
| CJA5E88TRD | CJ5E88TGRD |
| CJA5E88TVL | CJ5E88TGVL |
| CJA5E88TWH | CJ5E88TGWH |
| CJA5E88TYL | CJ5E88TGYL |
| CJA688TGBL | CJ688TGBL |
| CJA688TGBU | CJ688TGBU |
| CJA688TGEI | CJ688TGEI |
| CJA688TGGR | CJ688TGGR |
| CJA688TGIG | CJ688TGIG |
| CJA688TGIW | CJ688TGIW |
| CJA688TGOR | CJ688TGOR |
| CJA688TGRD | CJ688TGRD |
| CJA688TGVL | CJ688TGVL |
| CJA688TGWH | CJ688TGWH |
| CJA688TGYL | CJ688TGYL |
| CJA688TPBL | CJ688TGBL |
| CJA688TPBU | CJ688TGBU |
| CJA688TPEI | CJ688TGEI |
| CJA688TPGR | CJ688TGGR |
| CJA688TPIG | CJ688TGIG |
| CJA688TPOR | CJ688TGOR |
| CJA688TPRD | CJ688TGRD |
| CJA688TPVL | CJ688TGVL |
| CJA688TPWH | CJ688TGWH |
| CJA688TPYL | CJ688TGYL |
| CJA6X88TGBL | CJ6X88TGBL |
| CJA6X88TGBU | CJ6X88TGBU |
| CJA6X88TGEI | CJ6X88TGEI |
| CJA6X88TGGR | CJ6X88TGGR |

| | |
|-------------|------------|
| CJA6X88TGIG | CJ6X88TGIG |
| CJA6X88TGIW | CJ6X88TGIW |
| CJA6X88TGOR | CJ6X88TGOR |
| CJA6X88TGRD | CJ6X88TGRD |
| CJA6X88TGVL | CJ6X88TGVL |
| CJA6X88TGWH | CJ6X88TGWH |
| CJA6X88TGYL | CJ6X88TGYL |
| CJA6X88TPOR | CJ6X88TPOR |