

## **Product Change Notification**

Date
June 15, 2021

Product

Enterprise Cellular

# Description of change

New firmware version 21.5.56.106available for all Enterprise Cellular products. This is a major production release. Digi recommends all customers update their Enterprise Cellular products to firmware v21.5.56.106

### **Reason for Change**

New Firmware Version 21.5.56.106 provides:

- New Features
- Enhancements
- Bug Fixes
- Security Fixes

See Release Notes for more details.

### Product Notice

A new stable firmware version has been released for the Enterprise Cellular products, version 21.5.56.106. Use the link below to view the full list of changes, features, and fixes included in the new firmware.

**Enterprise Cellular Release Notes** 

<u>To take advantage of the new features, you must take action to update</u> <u>your device.</u> Refer to the instructions to update your firmware in the release notes above for more information.

Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team at <a href="mailto:tech.support@digi.com">tech.support@digi.com</a>.

#### **Affected Part Numbers**

ASB-EX15-XX04-OUS, ASB-EX15-XXE4-GLB, ASB-EX15-XX06-GLB, ASB-EX15-XX11-OUS, ASB-EX15-XC18-GLB, ASB-EX15-XX11-GLB, ASB-EX15-WX04-OUS, ASB-EX15-WXE4-GLB, ASB-EX15-WX06-GLB, ASB-EX15-WX11-OUS, ASB-EX15-WC18-GLB, ASB-EX15-

WX11-GLB, ASB-6310-DXE4-GLB, ASB-631R-DX03-OUS, ASB-631R-DX04-OUS, ASB-631R-DX06-OUS, ASB-631R-DX06-GLB, ASB-6300-CX02-OUS, ASB-6300-CX03-GLB, ASB-6300-CX05-GLB, ASB-6300-CX02-OUS, ASB-6355-SR03-GLB, ASB-6355-SR04-GLB, ASB-6355-SR06-GLB, ASN-6350-SR03-GLB, ASN-6350-SR04-GLB, ASN-6350-SR06-GLB, ASB-6330-MX03-OUS, ASB-6330-MX04-OUS, ASB-6330-MX06-GLB, ASB-6335-MX06-OUS, ASB-6335-MX06-OUS, ASB-6335-MX06-OUS

Timing of Change	Effective Immediately
------------------	-----------------------