

To: Fluke Distribution
From: Fluke Corporation
Date: 26 January 2022

Regarding: Fluke Thermal Imagers

Dear Fluke Channel Partner,

We are pleased to inform you that Fluke has resolved its battery supply chain issues. As of 31 January 2022, all below Fluke Thermal models will resume two batteries production and supply to the customers (some models remain subject to extended ATP time and availability).

At the same time, we will arrange to ship the 2nd battery to our customers who submitted the voucher registration at (www.fluke.com/Thermalbattery). The redemption shipments will begin in February. New voucher registrations will be accepted until 31 December 2022.

We appreciate your kind understanding and support during the one-battery supply period of time.

Item No	Item Desc	Market Model	Model Group	PFAM Code
5127977	FLK-TI300+ 9HZ,THERMAL IMAGER; GS2; 9 HZ	TI300+	GEM	TI
5127961	FLK-TI300+ 60HZ,THERMAL IMAGER; GS1; 60 HZ	TI300+	GEM	TI
5127992	FLK-TI400+ 9HZ/CN,THERMAL IMAGER; GS1; 9 HZ, CHINA	TI400+	GEM	TI
5085052	FLK-TI401-PRO 9HZ,THERMAL IMAGER; HS2; 9 HZ	TI401	GEM	TI
5085041	FLK-TI401-PRO 60HZ,THERMAL IMAGER; HS1; 60 HZ	TI401	GEM	TI
5085083	FLK-TI401-PRO 9HZ/CN,THERMAL IMAGER; HS2; 9 HZ, CHINA	TI401	GEM	TI
5085090	FLK-TI401-PRO 60HZ/J,THERMAL IMAGER; HS1; 60 HZ, JAPAN	TI401	GEM	TI
4947332	FLK-TI480-PRO 9HZ,THERMAL IMAGER; 640X480; 9 HZ	TI480	GEM	TI
4952450	FLK-TI480PRO60HZ/WWG,THERMAL IMAGER; 640X480; 60 HZ; WWG #453C43	TI480	GEM	TI
4947326	FLK-TI480-PRO 60HZ,THERMAL IMAGER; 640X480; 60 HZ	TI480	GEM	TI
4950040	FLK-TI480-PRO 9HZ/CN,THERMAL IMAGER; 640X480; 9 HZ, CHINA	TI480	GEM	TI
4950069	FLK-TI480-PRO 9HZ/MX,THERMAL IMAGER; 640X480; 9 HZ; MEXICO	TI480	GEM	TI
4950033	FLK-TI480-PRO 9HZ/BR,THERMAL IMAGER; 640X480; 9 HZ; BRAZIL	TI480	GEM	TI
4842168	FLK-TI480 9HZ/CN,THERMAL IMAGER; 640X480; 9 HZ, SR, CHINA	TI480	GEM	TI
4950025	FLK-TI480-PRO60HZ/JP,THERMAL IMAGER; 640X480; 60 HZ; JAPAN	TI480	GEM	TI
5133416	FLK-TIS60+ 9HZ/CN,THERMAL IMAGER; GT2; 9 HZ, CHINA	TIS60+	AURO	TI
5133402	FLK-TIS60+ 9HZ,THERMAL IMAGER; GT2; 9 HZ	TIS60+	AURO	TI
5133399	FLK-TIS60+ 30HZ,THERMAL IMAGER; GT1; 30 HZ	TIS60+	AURO	TI
5085128	FLK-TIX501 9HZ,THERMAL IMAGER; HS2; 9 HZ	TIX501	ORIO	TI
5085119	FLK-TIX501 60HZ,THERMAL IMAGER; HS1; 60 HZ	TIX501	ORIO	TI
5085143	FLK-TIX501 9HZ/CN,THERMAL IMAGER; HS2; 9 HZ, CHINA	TIX501	ORIO	TI
4841803	FLK-TIX580 9HZ/CN,THERMAL IMAGER; 640X480; 9 HZ, SR, CHINA	TIX580	ORIO	TI
4841945	FLK-TIX580 9HZ,THERMAL IMAGER; 640X480; 9 HZ, SR	TIX580	ORIO	TI
4842073	FLK-TIX580 60HZ,THERMAL IMAGER; 640X480; 60 HZ, SR	TIX580	ORIO	TI
4841906	FLK-TIX580 60HZ/CN,THERMAL IMAGER; 640X480; 60 HZ, SR, CHINA	TIX580	ORIO	TI
4841992	FLK-TIX580 9HZ/JP,THERMAL IMAGER; 640X480; 9 HZ, SR, JAPAN	TIX580	ORIO	TI
4842064	FLK-TIX580 9HZ/MX,THERMAL IMAGER; 640X480; 9 HZ, SR, MEXICO	TIX580	ORIO	TI
4873544	FLK-TIX580 60HZWWG,THERMAL IMAGER; 640X480; 60 HZ, SR, WWG #53DN16	TIX580	ORIO	TI

Sincerely,

Christina WANG

Christina WANG
BU Leader Fluke Routine Maintenance Product Group