

PRODUCT DISCONTINUATION

PD-ION-H8UI-13

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ION	CNC	Discontinuation	Notify Distributors and Field	10/4/2013

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

The following antenna cable part numbers have reached end of life and will no longer be able to be ordered once stock reaches 0

5606169 - RAD-CAB-LMR240-3
 2867364 - RAD-CAB-RG58-10
 2867212 - RAD-CAB-RG58-20
 2867597 - RAD-CAB-RG213-25

Replacement parts are available, please see listing below or contact technical service for alternates.

Warranty Information:

N/A

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? Y

Transaction Dates:

Last Buy from Phoenix Contact: Available until stock reaches 0

Last Scheduled Ship from Phoenix Contact: Available until stock reaches 0

PRODUCT DISCONTINUATION

Previous Product		(if applicable)	New Product	
				
Discontinued Part#	Type Description	Replacement Part#	Type Description	
5606169	RAD-CAB-LMR240-3	5606124	RAD-CAB-LMR240-10	
2867364	RAD-CAB-RG58-10	5606124	RAD-CAB-LMR240-10	
2867212	RAD-CAB-RG58-20	5606125	RAD-CAB-LMR400-20	
2867597	RAD-CAB-RG213-25	5606126	RAD-CAB-LMR500-25	

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

JUSTIN SHADE
(717)944-1300x3524
jshade@phoenixcon.com

Thank you,



Ira Sharp , Product Marketing Manager