



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631
www.littelfuse.com

Product Change Notice (PCN)

April 9th, 2021

Discontinuation Notice for FBMOV Varistor Series

To whom it may concern,

Littelfuse would like to inform you that the production of FBMOV Varistor Series has ceased, and the product has been discontinued effective immediately. We will not be able to accept any new orders or a last time buy.

Littelfuse has been forced to take this action as a key raw material supplier is no longer able to supply us with material to make FBMOV product.

Please see attached the discontinued and possible/similar replacement part number list.

Please contact your regional Littelfuse sales representative for more information and possible/similar replacement product information. Thank you for your continued support.

Best Regards

Littelfuse, Inc.

Part Number Status	Part Number
Discontinuation	FBMOV115M
Active/Possible/Similar Replacement	LST1505VL2NT1
Discontinuation	FBMOV130M
Active/Possible/Similar Replacement	LST1505VL2NT1
Discontinuation	FBMOV140M
Active/Possible/Similar Replacement	LST1505VL2NT1
Discontinuation	FBMOV150M
Active/Possible/Similar Replacement	LST1505VL2NT1
Discontinuation	FBMOV175M
Active/Possible/Similar Replacement	LST1805VL2NT1
Discontinuation	FBMOV230M
Active/Possible/Similar Replacement	LST2755VL2NT1
Discontinuation	FBMOV250M
Active/Possible/Similar Replacement	LST2755VL2NT1
Discontinuation	FBMOV275M
Active/Possible/Similar Replacement	LST2755VL2NT1
Discontinuation	FBMOV300M
Active/Possible/Similar Replacement	LST3205VL2NT1
Discontinuation	FBMOV320M
Active/Possible/Similar Replacement	LST3205VL2NT1
Discontinuation	FBMOV385M
Active/Possible/Similar Replacement	LST3855VL2NT1
Discontinuation	FBMOV420M
Active/Possible/Similar Replacement	LST4205VL2NT1
Discontinuation	FBMOV440M
Active/Possible/Similar Replacement	LST5105VL2NT1
Discontinuation	FBMOV460M
Active/Possible/Similar Replacement	LST5105VL2NT1
Discontinuation	FBMOV510M
Active/Possible/Similar Replacement	LST5105VL2NT1
Discontinuation	FBMOV550M
Active/Possible/Similar Replacement	LST5505VL2NT1
Discontinuation	FBMOV625M
Active/Possible/Similar Replacement	LST6905VL2NT1
Discontinuation	FBMOV750M