

## PRODUCT CHANGE NOTIFICATION 20190319-StrongHold PCN#: TIES AND TERMINALS **ISSUE DATE:** 20190319 ✓ AP **IMPACTED REGIONS:** $\square$ NA ✓ EMEA □ LATAM **REASON FOR CHANGE:** DISCONTINUATION √ OTHER **DESCRIPTION OF CHANGE: (Not Required for discontinuation)** The following StrongHold cable ties now include UL 181 certification (in addition to the UL 62275 certification these cable ties already possess): S18-175 S21-175 S24-175 S31-175 These ties are now covered under UL category ALKW (Air Duct and Air Connector Closure Systems) per UL 181. As such, these ties have now been subjected to both ANSI/UL 181B and ANSI/UL 181C, both of which cover ANSI/UL 723 "Test for Survace Burning Characteristic of Building Materials" and ANSI/UL 2043 "Fire Test for Heat and Visible Smoke Release for Discrete Products and Their Accessories Installed in Air-Handling Spaces." The key take-away from this is that these newly listed cable ties have been found to be suitable for use in plenums in accordance with the "International Mechanical Code", "Uniform Mechanical Code", and ANSI/NFPA 90A "Installation of Air-Conditioning and Ventilating Systems." Error Correction: Maximum Bundle Diameter for S18-175-L and S18-175-LO cable ties Part numbers S18-175 were incorrectly stated as Max. Bundle Diameter of 5.20" (132mm). The correct information on this size cable tie is 4.92" (125mm). Corrected info is being addressed as a running change. Photos/Drawing (where applicable) IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

(Running Change)

## DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2019	4	30
Old product discontinuation date*			

<sup>\*</sup>Important: After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

FORM C2-1003 DATE: 21JUN18 APPR: GKH WWW.PANDUIT.COM

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
S18-175-L	
S18-175-L0	
S21-175-L	
S21-175-C	
S21-175-L0	
S21-175-C0	
S24-175-L	
S24-175-L0	
S31-175-L	
S31-175-L0	