




PRODUCT OBSOLESCENCE MEMO

LINE PROTECTION MODULES



SEMS Line Protection Modules (LPMs) and Hybrid Modules using Thick Film to be Discontinued

Riverside, California - August 9, 2022 – In accordance with our ongoing product life cycle management procedure, Bourns will transfer select [Line Protection Modules](#) (LPMs) and Hybrid Modules using thick film to an End of Product Life status on August 30th, 2022. A lack of sales volume and diminishing demand necessitates this action. A list of obsolete part numbers is provided on the following page.

No replacement part numbers are available at this time. Customers may continue to purchase the affected part numbers during the End of Product Life transition period between now and August 30th, 2022. Orders for these part numbers during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: **August 30th, 2022**

Last time ship date: **December 31st, 2022**

Affected Part Numbers					
4618H-BK4-00CLF	4B06B-512-5R6	C4817	C6231	N4985	N5762
4A08P-560-015	4B06B-512-5R6JLF	C4900	C6247	N4985LF	N5763
4A08P-CJ8-911	4B06B-514-500	C4948	C6248	N5030	N5766
4A08P-CJ8-911LF	4B06B-522-500	C5005	C6250	N5032	N5897
4A08P-CM2-400	4B06B-522-500LF	C5058	C6291	N5057	N5940
4A08P-CM3-201	4B06B-540-095/095	C5058LF	C6291LF	N5100	N5997
4A12P-1AH-12R5	4B06B-BL6-000	C5106	C6315	N5155	N5997LF
4A12P-1AK-100	4B06B-BM2-000	C5183	C6317	N5174	N6030
4A20P-ALR-000	4B06B-BR9-000	C5214	C6332	N5232	N6040

(continues on page 2)

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

L2201

Affected Part Numbers (continued)

4A24P-AJJ-151	4B06B-BS2-000	C5298	C6336	N5232LF	N6055
4B04B-501-210	4B06B-BS2-000LF	C5306	C6347	N5234LF	N6191
4B04B-501-500	4B06B-BT1-000	C5320	C6370	N5235	N6200
4B04B-502-100F	4B06B-BV1-000	C5375	C6381	N5235LF	N6208
4B04B-502-100J	4B06B-CB9-000	C5388	C6403	N5238	N6209
4B04B-502-16R9F	4B06B-CU7-090/200A	C5452	C6428	N5241	N6232
4B04B-502-200	4B06B-CU7-160	C5483	C6436	N5241LF	N6287
4B04B-502-4R7J	4B06B-CU7-275	C5565	C6439	N5243LF	N6289
4B04B-502-5R6F	4B06B-CU9-100	C5590	C6443	N5247	N6313
4B04B-502-5R6J	4B06B-CU9-150	C5590LF	C6443LF	N5247LF	N6314LF
4B04B-502-5R6JLF	4B06B-CU9-200	C5601	C6465	N5248LF	N6319
4B04B-523-200	4B06B-CW3-000	C5625	C6523	N5302	N6330
4B04B-523-400	4B07B-AS9-000	C5637	C6536LF	N5324	N6330F
4B04B-523-500LF	4B07B-DE1-400	C5653	N3012	N5391	N6350
4B04B-524-200	4B08B-503-500	C5693	N3139	N5434	N6372
4B04B-524-400	4B08B-513-500	C5753	N3140	N5440	N6375
4B04B-524-500LF	4B08B-513-500LF	C5768	N3178	N5440LF	N6389
4B04B-BA5-000	4B08B-AKK-5R6	C5857	N4057	N5446	N6390
4B04B-BS8-000	4B08B-AKK-7R5	C5893	N4106	N5485	N6392
4B04B-CE1-100F	4B08B-AKL-5R6LF	C5894	N4119	N5491	N6397
4B04B-CE1-5R6J	4B08B-BP8-000	C5901	N4120	N5492	N6397F
4B04B-CR4-000	4B08B-BT3-000	C5910	N4146	N5493	N6404
4B05B-BP5-000	4B08B-BT3-000LF	C5941	N4535	N5494	N6415
4B05B-DN1-000LF	4B10B-BAA-000	C5946	N4536	N5495	N6426
4B06B-1AA-075/190	4B10B-CN9-000	C5959	N4643	N5496	N6427
4B06B-1AA-160	4B12B-BR1-000	C5974	N4676	N5497	N6429
4B06B-1AA-275	4B12B-CC6-000LF	C5974LF	N4677	N5512	N6434
4B06B-1AB-275	4B12B-P91-000	C5978	N4698	N5515	N6442
4B06B-1AG-275	4B12B-P92-000	C5996	N4899	N5561	N6476
4B06B-504-101	4B13B-BH8-000	C6010	N4904LF	N5664	N6478
4B06B-504-500LF	4B13B-BH8-000LF	C6110LF	N4920	N5687	N6481
4B06B-512-100LF	4B20B-DS1-000	C6162	N4968	N5740	N6485
4B06B-512-200	C4201	C6173	N4969	N5742	N6493
4B06B-512-200LF	C4679	C6202	N4979	N5743	N6494
4B06B-512-500LF	C4746LF	C6210	N4983	N5757	N6500

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).