

PRODUCT DISCONTINUATION NOTICE

PDN No.: USA2014/005

IXTK	PRODUCT TYPE: 20N140, IXTX20I 2N140, IXTT12N	N140,	POWER MOSFET	RECOMMEND REPLACEMENTS: IXTK20N150, IXTX20N150, IXTH12N150, IXTT12N150
THE RECOMMENDED REPLACMENT IS THE <u>EXACT SAME</u> DEVICE, HOWEVER THESE DEVICES ARE ELECTRICALLY TESTED FOR 1500V AND MARKED FOR 1500V GRADE.				
REASOI	N FOR DISCONTINUA	TION: NO MARKET DEN	MAND	
LAST TI	ME ORDER DATE:	N/A		
LAST TI	ME DELIVERY DATE:	N/A		
INTERN	AL REFERENCE:	N/A		
INITIATO		contact: Sudhir Kominnen TITLE/FUNCTION DEPT. HEAD QA	i IXYS Gen Mgr. , IXYS Milpit DATE JUNE 10. 201	tas USA E-mail: s.kominneni@ixys.net E-MAIL G.ROSETE@IXYS.NET
CUSTOMER RESPONSE: (PLEASE FILL IN AND RETURN BY E-MAIL, FAX OR MAIL WITHIN 4 WEEKS)				
(I ELACE I LE NAME METONIA DE ENVALE, LAN ON MAIL MITTINA 4 MELLINO)				
	for further questions/	information	. ,	
	please comment			
COMMENTS:				

IF 0266 Rev.0 (01.26.10) Page 1 of 1 Reference QS 0073