



To : Dear Valued Customers

Product Discontinuance Notice

| Subject : CDBD5xx Series and CDBVFHT160 products discontinue. | | | | | | | | | | | | | | | |
|--|--|------------------|---------------|-------------|------------|-------------|------------|-------------|-------------|-------------|-------------|-------------|---------------|-----------|--|
| Parts Affected : | | | | | | | | | | | | | | | |
| <table border="1" style="margin: auto; border-collapse: collapse;"> <thead> <tr> <th style="padding: 5px;">Part No.</th> <th style="padding: 5px;">Package Type</th> </tr> </thead> <tbody> <tr> <td style="padding: 5px;">CDBD540-HF</td> <td style="padding: 5px;">TO-252/DPAK</td> </tr> <tr> <td style="padding: 5px;">CDBD545-HF</td> <td style="padding: 5px;">TO-252/DPAK</td> </tr> <tr> <td style="padding: 5px;">CDBD560-HF</td> <td style="padding: 5px;">TO-252/DPAK</td> </tr> <tr> <td style="padding: 5px;">CDBD5150-HF</td> <td style="padding: 5px;">TO-252/DPAK</td> </tr> <tr> <td style="padding: 5px;">CDBD5200-HF</td> <td style="padding: 5px;">TO-252/DPAK</td> </tr> <tr> <td style="padding: 5px;">CDBVFHT160-HF</td> <td style="padding: 5px;">SOD-323ST</td> </tr> </tbody> </table> | Part No. | Package Type | CDBD540-HF | TO-252/DPAK | CDBD545-HF | TO-252/DPAK | CDBD560-HF | TO-252/DPAK | CDBD5150-HF | TO-252/DPAK | CDBD5200-HF | TO-252/DPAK | CDBVFHT160-HF | SOD-323ST | |
| Part No. | Package Type | | | | | | | | | | | | | | |
| CDBD540-HF | TO-252/DPAK | | | | | | | | | | | | | | |
| CDBD545-HF | TO-252/DPAK | | | | | | | | | | | | | | |
| CDBD560-HF | TO-252/DPAK | | | | | | | | | | | | | | |
| CDBD5150-HF | TO-252/DPAK | | | | | | | | | | | | | | |
| CDBD5200-HF | TO-252/DPAK | | | | | | | | | | | | | | |
| CDBVFHT160-HF | SOD-323ST | | | | | | | | | | | | | | |
| Reason for Discontinuance : | | | | | | | | | | | | | | | |
| Due to low demand, the part listed below will be discontinued. | | | | | | | | | | | | | | | |
| Alternative Products : | | | | | | | | | | | | | | | |
| 1. CDBD5xx-HF Series please contact sales person or manufacturer's representative. | | | | | | | | | | | | | | | |
| 2. | | | | | | | | | | | | | | | |
| <table border="1" style="margin: auto; border-collapse: collapse;"> <thead> <tr> <th style="padding: 5px;">EOL p/n.</th> <th style="padding: 5px;">Alternative p/n.</th> </tr> </thead> <tbody> <tr> <td style="padding: 5px;">CDBVFHT160-HF</td> <td style="padding: 5px;">CDBFN160-HF</td> </tr> </tbody> </table> | EOL p/n. | Alternative p/n. | CDBVFHT160-HF | CDBFN160-HF | | | | | | | | | | | |
| EOL p/n. | Alternative p/n. | | | | | | | | | | | | | | |
| CDBVFHT160-HF | CDBFN160-HF | | | | | | | | | | | | | | |
| Effective Date : Mar 31, 2022 | | | | | | | | | | | | | | | |
| R&D Dept. Signature : | QA Dept. Signature : | | | | | | | | | | | | | | |
|  |  | | | | | | | | | | | | | | |