



Product Change Notification

TE Connectivity

Product Change Notification: PCN-21-118794

PCN Date: 26-OCT-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
DEUTSCH DT Wedges Material Change

Description of Changes
The Industrial and Commercial Transportation business unit of TE Connectivity is making a material change to the DT wedge locks resin for the part numbers listed below. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. Product drawings are not affected.

Reason for Changes:
Dear Customer, we hereby inform you of this change as part of our continuous improvement efforts. The flammability rating on the newly approved wedge lock material is V-0 while the current one is HB. The current and the new raw materials are PBT 30G. Change does not affect fit, form and function. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change is being phased in gradually and previous revision can remain stocked until use.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-JAN-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	28-APR-2023

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF000000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF000000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF000000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2S	NO			"ZPF000000000131424"			
W2S-P012	NO			"ZPF000000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF000000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L", "8202608764", "73000932-F"			
W3P-1939	NO			"ZPF000000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF000000000131437"			
W3S-P012	NO			"ZPF000000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF000000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF000000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF000000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF000000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF000000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W8S-P012	NO			"ZPF000000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS", "8202606748"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W3S	NO			"W3S-AS"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF000000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF000000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF000000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2S	NO			"ZPF000000000131424"			
W2S-P012	NO			"ZPF000000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF000000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L", "8202608764", "73000932-F"			
W3P-1939	NO			"ZPF000000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF000000000131437"			
W3S-P012	NO			"ZPF000000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF000000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF000000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF000000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF000000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF000000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF000000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF000000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF000000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2S	NO			"ZPF000000000131424"			
W2S-P012	NO			"ZPF000000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF000000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L", "8202608764", "73000932-F"			
W3P-1939	NO			"ZPF000000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF000000000131437"			
W3S-P012	NO			"ZPF000000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF000000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF000000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF000000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF000000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF000000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2S	NO			"ZPF000000000131424"			
W3S	NO			"W3S-AS"			
W4P	NO			"ZPF000000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF000000000131462", "W12P-AS", "W12P-P004-M"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12S	NO			"ZPF000000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF000000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$SW12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2S	NO			"ZPF000000000131424"			
W2S-P012	NO			"ZPF000000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$SW2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF000000000131434", "W3P-AS", "W3P-LS", "\$SW3P", "W3P-L", "8202608764", "73000932-F"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF000000000131437"			
W3S-P012	NO			"ZPF000000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$SW3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF000000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF000000000131455", "W6P-AS", "\$SW6P"			
W6S	NO			"ZPF000000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF000000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF000000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF000000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF000000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$SW12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2S	NO			"ZPF000000000131424"			
W2S-P012	NO			"ZPF000000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$SW2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF000000000131434", "W3P-AS", "W3P-LS", "\$SW3P", "W3P-L", "8202608764", "73000932-F"			
W3P-1939	NO			"ZPF000000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF000000000131437"			
W3S-P012	NO			"ZPF000000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$SW3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF000000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF000000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF000000000131455", "W6P-AS", "\$SW6P"			
W6S	NO			"ZPF000000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF000000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			
W8S-P012	NO			"ZPF000000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			