



Product Change Notification

TE Connectivity

Product Change Notification: P-20-019225

PCN Date: 30-JUN-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Qualification of EMEA Tubing Products to be Manufactured in Shanghai China for use in Asia Pacific region.

Description of Changes

Manufacturing location change. In support of our Asia Region customers the following Part Numbers will be manufactured in Shanghai, China.

Other attachments:

[PCN Products to Shanghai](#)

[PCN Products to Shanghai affected parts](#)

Reason for Changes:

Customer Request. Dear Customer, as a result of our continuous strive for improving our processes, we have qualified the local manufacturing of the following Tubing Product Families for manufacturing in Shanghai, China: ES1000, ES CAPS, and FL2500. Affected products and part numbers can be found in the support document. The Shanghai manufacturing facility is an already established Heat Shrinkable Tubing manufacturing site since 1996. PPAP and samples will be available from TE Shanghai and can be requested through your local TE Connectivity Customer Service associate.

Estimated Dates:

Last Order Date (Obsolete Parts Only): **First Date To Ship** (Changed Parts Only):

28-SEP-2020

Last Ship Date (Obsolete Parts Only): **Last Date for Mixed Shipments:** (Changed Parts Only):

29-SEP-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0081930003	NO			"4-1190063-2", "ES-CAP-NO.1-C1-X-35MM"			
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0081930003	NO			"4-1190063-2", "ES-CAP-NO.1-C1-X-35MM"			
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
3371890005	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0081930003	NO			"4-1190063-2", "ES-CAP-NO.1-C1-X-35MM"			
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			