

Product change information

Topic NEO-M8L, NEO-M8U: New order codes

UBX-20053641 C1-Public

Author Martin Wallebohr, Mathias Vetter

Date 22 January 2021

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit www.u-blox.com.
Copyright© u-blox AG.

1 Affected products

Product name	Old order codes	New order code	New firmware version
NEO-M8L	NEO-M8L-05B NEO-M8L-04B NEO-M8L-0	NEO-M8L-06B	ADR 4.50
NEO-M8U	NEO-M8U-05B NEO-M8U-04B NEO-M8U-0	NEO-M8U-06B	UDR 1.50

2 Type of change

- Hardware modification
- Firmware update
- Documentation update
- Other: new part number

3 Description

NEO-M8U and NEO-M8L use an inertial measurement unit sensor (IMU). The sensor being used today has limited availability due to a shortage of IMU sensors on the market.

To improve the resilience of our supply chain u-blox has selected new IMU sensors for professional grade NEO-M8L and NEO-M8U which fulfil the u-blox performance requirements given in the data sheets.

The product specifications, overall performance and characteristics of the product remain unchanged.

Using the new IMU sensor requires updating the existing firmware with new SW drivers resulting in new firmware versions, namely ADR 4.50 for NEO-M8L and UDR 1.50 for NEO-M8U.

4 Schedule for new order codes

Product name	Order code	Availability
NEO-M8L	NEO-M8L-06B	Feb 2021 (ES), Mar 2021 (IP)
NEO-M8U	NEO-M8U-06B	Feb 2021 (ES), Mar 2021 (IP)

5 Customer impact and recommended action

It is mandatory to select new part numbers as the old part numbers cannot be supplied any more. For open orders please approach your local sales contact to switch existing orders into the new order code.

We thank you for your understanding and assure you our very best support.

6 Q&A

Q: What impact on performance will the new IMU sensor have?

New IMU sensor generation has better performance which is visible in tunnels/parking garages. However, u-blox does not expect any changes on performance figures given in the data sheets today.

Q: Will there be a second source available for new part numbers?

Yes, there will be two different IMU sensors fully qualified for the new part numbers to secure u-blox supply chain.

Q: Can customer choose which IMU sensor will be used?

No, customers cannot choose the IMU sensors. Both sensors are validated and fulfil the performance criteria given in the data sheet.