



Product/Process Change Notice - PCN 11_0309 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Material Report). Any issues with this PCN or requirements to qualify the change (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

PCN Title: ADMP401 Pocket Tape Update

Publication Date: 16-Dec-2011

Effectivity Date: 15-Mar-2012 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Initial Release

Description Of Change

The ADMP401's orientation in ADI's standard pocket tape is changing.

Currently, the ADMP401 is loaded into pocket tape so that pin 1 is at position C1 described in ADI's tape and reel document (upper left-hand corner if sprocket holes are upward).

After this change, all ADMP401 material will be loaded into the pocket tape so that pin 1 is at position C3 (lower right-hand corner of tape if sprocket holes are upward).

Reason For Change

All other ADI products using the 4.76x3.72x1.00mm LGA package are mounted into pocket tape at position C3. This change standardizes the ADMP401 to the same orientation.

Impact of the change (positive or negative) on fit, form, function & reliability

There is no change to fit, form, function, or reliability.

Product Identification *(this section will describe how to identify the changed material)*

All product shipped with a date code of 1213 and later will use the new pocket tape orientation. Everything prior to that date code will use the original pocket tape orientation.

Summary of Supporting Information

ADI's standard tape and reel orientation diagram provides a full description of the tape and is helpful in understanding the change. See attached document.

Supporting Documents

Attachment 1: Type: Detailed Change Description

ADI_PCN_11_0309_Rev_-_ADMP401 Pocket Tape Orientation Change Description 12_8_2011.docx

For questions on this PCN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PCN_Americas@analog.com

Europe: PCN_Europe@analog.com

Japan: PCN_Japan@analog.com

Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models

Added Parts On This Revision - Product Family / Model Number (2)

ADMP401 / ADMP401ACEZ-RL	ADMP401 / ADMP401ACEZ-RL7			
--------------------------	---------------------------	--	--	--

Appendix B - Revision History

Rev	Publish Date	Rev Description
Rev. -	16-Dec-2011	Initial Release

Analog Devices, Inc.

DocId:1794 Parent DocId:None Layout Rev:6